

Step-by-step plan removal iron clip SC-APC adapter

As long as the iron clip is attached to the SC-APC adapter, it won't be possible to place the adapter in the ONTP. In this short guide it will be explained how to remove the iron clip of the adapter.





Step 1: Removal iron clip

SAP code 90046571 - **Attention: Unit is pack of 50 pcs!**
FTTH ONTP EXTRA APC ADAPTER PAC 50 pcs
Article code Crosswise: 001341



← SC-APC adapter with iron clip


Press the iron clip down the side of the adapter.



Now push the metal clip upwards to remove it.




Step 2: Placing the SC-APC adapter in the ONTP



← NEVER place the adapter with iron clip in the ONTP!

Correct way:
Always place the SC-APC adapter in the ONTP as can be seen in the picture.



No responsibility is taken for the correctness, currency and completeness of details and information.
Liability for damages is excluded.